

MICROGUARD[®]

HVAC

Corporate Headquarters
1901 Mason Ave, Suite 101
Daytona Beach, FL 32117

Toll Free: 800.549.2539
Phone: 386.274.1382
Fax: 386.274.1798
www.adsil.com

CASE STUDY: Gaidos Seafood Restaurant — Galveston, Texas



Cabinet shines like new!



No corrosion on the coil edges!

Situation: Galveston, Texas Seawall, is a highly corrosive coastal environment.

Solution: Condenser coils were being replaced each year in this harsh, coastal environment. New American Standard equipment was treated with Adsil MicroGuard[®] AD35 Coil & Fin Protective Treatment, in April of 2002. Cabinetry, screws, coils & fins and interior support metal were coated.

Results: After 18 months, the coils/fins, cases and fan blades are all in excellent condition. Fins are attached to coil tubes resulting in the retention of conductive heat transfer and designed energy efficiency. Fins are pliable and can be bent without breaking or cracking.