

## CASE STUDY: Providence Hospital Restroom Tile Floors – Mobile, AL



**Situation:** A competitive urethane coating had been installed on the tile floors, which had prematurely become deeply scratched, had dulled in appearance and was difficult to clean and maintain.

**Solution:** The non-performing urethane coating was stripped, the tile was deep cleaned and the MicroGuard tile system was installed by Cornerstone H.S.R., a premier Adsil Certified Installer.

**Results:** Another happy and satisfied customer. The tile floor looks great, the exceptionally durable MicroGuard coating resists scratching, gloss is maintained and the hydrophobic characteristics of this patented, reacted siloxane clear-coat renders it easy to clean and maintain...a most important benefit within hospital environments.