

## CASE STUDY: Pittsburg High School, Pittsburg, California Main Entry into School Building



**Before** – severe staining of brick, grime deeply impregnating mortar, chewing gum hardened on surface and almost impossible to remove.



**After** – decorative brick is beautifully renewed and sealed from further staining or grime penetration. Baked on chewing gum releases with minimal effort.



**Problem:** Graduation ceremonies were just weeks away, but the school decorative brick entry was unsightly, due to chewing gum deposits, impregnated dirt and grime-filled mortar joints. School officials turned to MicroGuard for the solution.

**Solution:** Alldura, a Certified Installation Company, applied MicroGuard AD703 Clear Concrete Sealer to the decorative brick entry. The hydrophobic film of AD703 now makes cleaning maintenance easier and expelled chewing gum is more easily removed. **The results were stunning**, declared school officials!