

Revised 03/11

Corporate Headquarters 1901 Mason Ave, Suite 101 Daytona Beach, FL 32117

Toll Free: 800.549.2539 Phone: 386.274.1382 Fax: 386.274.1798 www.adsil.com

CASE STUDY: Public Restroom Tile Floor, Chicago, Illinois





SITUATION: The restroom tile had heavy wax build up causing yellow discoloration of the tile, severe dirt impregnation in the grout and a general unsightly and unsanitary condition.

SOLUTION: After thorough deep cleaning, per Adsil published instructions, MicroGuard Hard Tile Clear Gloss Treatment was installed.

RESULTS: The grout lines were restored to the original white color and were sealed from further staining and discoloration. The tile surface is stunningly beautiful and ease of cleaning maintenance has been dramatically improved.

