

## CASE STUDY: US Bank Brick Paver Entrance, Marblelife of Kentucky



**Situation:** Paver Bricks & Grout were so inundated with grime that it was impossible to distinguish the original appearance.

**Solution:** Marblelife of Kentucky cleaned away the grime, sealed and finished the Paver Bricks with the MicroGuard System.

**Results:** A stunningly beautiful result that left the US Bank Manager speechless and amazed.